


# Blue Print ADH23414, ADH23607

to fit:  
Honda Accord 7/98 > 3/03



EN

## HONDA ACCORD – CLUTCH MASTER CYLINDER APPLICATION

### Application Guide Honda Accord 7/98 > 3/03

We have been made aware that Honda has suffered a supply problem on the Clutch Master Cylinder fitted to some early UK specification Honda Accord models 1998 to 2003.

The Clutch Master cylinder that was fitted on the production line has now been discontinued and is not available as a replacement part.

Honda's fix to this problem is to supply the later Clutch Master Cylinder as a replacement, but this means that all other parts in the clutch operating system (Clutch pipes, clutch slave cylinder etc) also have to be replaced to allow the later Clutch Master Cylinder to be fitted. This means customers have to purchase extra parts to get the vehicle back on the road.

The Blue Print part number **ADH23414** is also of the later design due to the early design not being produced by the manufacturers anymore.

Due to this issue, customers will have to obtain the compatible pipe work from a Honda dealer. The Clutch Slave Cylinder is available from Blue Print – Part number **ADH23607**.

For more technical information please visit: [partsfinder.bilsteingroup.com](https://partsfinder.bilsteingroup.com)